



---

# Wash & Care Symbols

---

JAPAN

# JAPANESE WASH CARE SYMBOLS

---

For the Japanese labelling standards, there are 6 main sections appearing in the following order - washing, bleaching, ironing, dry-cleaning, wringing and drying.

## Washing



Washable - maximum temperature 95°C



Machine washable - with slow water current or gently by hand - maximum temperature of 30°C



Machine washable - maximum temperature 60°C



Gently hand wash only - maximum temperature 30°C



Machine washable - maximum temperature 40°C



Cannot be washed with water



Machine washable - with slow water current or gently by hand - maximum temperature of 40°C

## Bleaching



Chlorine-based bleaching allowed



Do not use chlorine-based bleach

## Ironing



Ironed at high temperature  
(between 180°C - 210°C)



Ironed at low temperature  
(between 80°C - 120°C)





Ironed at medium temperature  
(between 140°C - 160°C)




Cannot be ironed


## Dry-cleaning

 Can be dry-cleaned. Use solvent of perchloroethylene or petroleum - based matter

 Can be dry-cleaned  
Use petroleum - based solvent


 Cannot be dry-cleaned


## Wringing


 Wring gently


 Cannot be wrung

## Drying

 Hung to dry

 Laid down to dry

 Hung to dry in the shade

 Laid down to dry in the shade

[www.ukpaccessories.com](http://www.ukpaccessories.com)

[enquiries@ukpaccessories.com](mailto:enquiries@ukpaccessories.com)

**U.K.P. Accessories**  
garment branding, labelling & packaging